

Hawk A Model A Ford Club

Recommended Spare Parts and Tools for Touring

Be Prepared for Touring

The following list of tools, parts and supplies is a good checklist when preparing your car for a tour.

TOOLS	PARTS (pre-tested if possible!)
Jack and handle	Spark plug connectors
Starting crank	High tension coil lead
Tire pump	Fan belt
Ball peen hammer	Radiator hose set
Socket Wrench set 5/16-7/8	Light bulb set
Adjustable wrench, 10"	Water pump packing
Box wrench 5/8 x 3/4 (generator)	Ignition Switch
Box wrench 1/2 x 9/16 (battery)	Ignition points
Screwdrivers – flat blade and phillips	Condenser
Pliers	Spark plug(s)
Wire cutter/crimper/stripper	Ammeter
Ignition tools (feeler gauge, file)	Ignition cable
Grease gun	Generator cutout
Flashlight	Tie rod and drag link spring
Tube patch kit	Timing gear
Electrical circuit tester	Brake spring assortment
Distributor shaft wrench	Stop light switch
Tire irons (2)	Starter switch
Knife, Scout type	Starter drive
Scissors (for gasket work)	Coil
Emergency flares or flashers	Fuel lines and fittings
Spark plug wrench that fits YOUR plugs	
Model A adjustable wrench	
Drift, 5/8" diameter, brass	
Drift, steel	
Socket, main bolts	
½" Open End Wrench – Timing Pin	

SUPPLIES	
Copper wire, #12 insulated, 10'	Carburetor gaskets
Bailing wire, iron, 10'	Sanding paper, fine grade
Heavy string	Soap and talcum (for tires)
Electrical tape	Length of wood (2x4 x6")
Assorted bolts, nuts, cotter pins, etc	Wheel bearing grease
Gasket sealing compound	Service manual
Gasket material, 12" square	Fuel valve packing
Gallon of Water	Small springs assortment
Fuses	Rags
3' siphon tubing	